

A detailed cross-sectional schematic diagram of a mechanical assembly, likely a semiconductor processing machine. The diagram shows a main body 10 supported by a base. A vertical column 40 is on the right. A horizontal arm 30 is on the left, holding a component 22. A central vertical shaft 50 is at the top. Various other components are labeled with numbers: 21, 31, 51, 52, and 32. Section lines S1 and S2 are indicated.




FIG. 2
Related Art




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8

